

Appendix C: Dunwoody Full Inventory

Dunwoody Park System	Total Acentage	
	Count	Units
Existing Amenities	161.82	
Playgrounds	5	EA
Shelters	15	EA
Restrooms	6	EA
Misc Structures	11	EA
Water Feature	2	EA
Baseball Fields	2	EA
Multi-purpose Field (unprogrammed)	3	EA
Bocce Ball Courts	2	EA
Tennis Court	2	EA
Basketball Courts	2	EA
Amphitheater	1	EA
Greenhouse	1	EA
Skate Park	1	EA
Outdoor Classrooms	3	EA
Community Garden	2	EA
Hammock Areas	1	EA
Dog Park	1	EA
Stage	1	EA
Fitness Equipment	10	EA
Main Signs	12	EA
Secondary Signs	3	EA
Wayfinding/MUTCD Signs	50	EA
Interpretive Signs	9	EA
Benches	115	EA
Picnic Tables	52	EA
Chairs	10	EA
Water Fountains	8	EA
Bench Swing	1	EA
Bollards	48	EA
Grills	1	EA
Trashcans	74	EA
Bike Racks	3	EA
Mutt Mitt Stations	25	EA
Bridges (wooden)	17	EA
Paved Trails	12027	LF
Unpaved Trails	12263	LF
Boardwalk	275	LF

Community Park		Total Acreage				
Dunwoody Park and Nature Center		33.3				
Type	Existing Amenities	Count	Units	Manufacturer	Condition ^(**)	Notes
Shelters and Playgrounds	Playground	1	EA		Good	Installed 2015
	2-5	1	EA	Miracle (Hasley Recreation)	Good	Forest, Green, Brown
	5-12	1	EA	Miracle (Hasley Recreation)	Good	Forest, Green, Brown
	Swings	3	EA	Miracle (Hasley Recreation)	Good	Two Miracle Accelerator Swings (Model 2014J), one Viper Gaint Rope Swing (Model 2015J)
	Other Equipment	3	EA	Multiple	Good	Miracle: One Gravity Cube (Model 447-4), one Multi-Pondo (Model 150-660), Other : Rope Climber
	Surfacing			EWf	Average	
	Benches	5	EA	Wabash Valley	Good	Green and Black
	Picnic Tables	4	EA		Average	Metal with wood top, two green and two brown
	Trashcans	2	EA	Wabash Valley	Average	Green
	Restrooms	2	EA		Average	Restroom #1 at ballfields includes storage and concession, restroom #2 is attached to Nature Center
Fields	Baseball Field #1	1	EA		Average	
	Bleachers	4	EA		Average	Metal bleachers
	Scoreboard	1	EA		Average	Not in operation at time of visit
	Benches	2	EA	Wabash Valley	Good	Green and Black
	Baseball Field #2	1	EA		Average	
	Bleachers	2	EA		Poor	Concrete bleachers with noticable deterioration
Other Facilities	Scoreboard	1	EA		Average	Not in operation at time of visit
	Picnic Tables	3	EA		Poor	Wood with metal base, green
	Benches	1	EA	Wabash Valley	Good	Green and Black
	Nature Center	1	EA		Good	
	Misc. Structure #1	1	EA		Poor	Storage and Umpire Building for Field One.
	Misc. Structure #2	1	EA		Average	Treehouse overlooking wetland
	Misc. Structure #3	1	EA		Good	Cabin
	Misc. Structure #4	1	EA		Poor	Wood structure (oversized kiosk)
	Benches	1	EA		Poor	Wood bench
	Misc. Structure #5	1	EA		Poor	Wood structure with metal pole, near picnic area behind playground
	Community Garden	1	EA			
	Outdoor Classroom	3	EA			Near hammock area; near nature center stage; near community garden
	Hammock Area	1	EA			
	Stage	1	EA		Average	Patio area stage with fireplace
Individual Park Items	Main Sign	3	EA		Average	Dunwoody parks brand sign with stone base; upright parks brand sign; Nature Center large kiosk sign
	Secondary Signs	2	EA		Average	Dunwoody Nature center signs
	Wayfinding MUTCD Signs	3	EA		Average	Map sign; Sanctuary and trails sign; Bulletin Kiosk
	Interpretive Signs	9	EA		Average	
	Benches	13	EA		Good	Seven Wabash; Six wooden
	Picnic Tables	13	EA		Average	Wood with metal base; Five green, seven brown, one metal with four chairs
	Chairs	10	EA		Good	Adirondack chairs
	Trashcans	4	EA		Average	Wooden; near nature center
	Mult Mitt Station	2	EA		Average	
	Bridge (wooden)	10	EA		Average	
	Unpaved Trails	8954	LF			
Boardwalk	275	LF		Average		

^(*)Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations.
^(**) Playground condition is based on visual inspection only and is not intended to be a GPSI level inspection.
^(***)GPS locations have been provided for all fixed park items, all moveable amenities are not included.

Neighborhood Park		Total Acreage				
Pernoshal Park		5.67				
Existing Amenities	Count	Units	Manufacturer	Condition**(*)	Notes	
Shelters and Playgrounds	Playground	1	EA	Miracle		
	2-12	2	EA	Miracle	New	DNA Climber, Nexus Velocity
	Surfacing			EPDM	New	
	Benches	2		Victory Stanley	New	Model C-138
	Shelter and Restroom	1	EA		New	Stone, Wood, Standing seam metal roof
	Trashcans	2	EA	Victory Stanley	New	Model FC-12, Black
	Water Fountains	2	EA			Attached to structure
Fields	Multi-purpose Field (unprogrammed)	2	EA			Not present at time of visit (proposed in park's master plan)
Courts	Basketball Court	2	EA		New	
	Playing Surface					No markings at time of visit
	Goals	4		Ironclad Sports, Inc.	New	Model HIL664-XXL
	Nets					Not installed at time of visit
	Benches	7		Victory Stanley	New	Backless Model CM-158
Other	Trashcans	2		Victory Stanley		Model FC-12, Black
	Amphitheater	1	EA		New	
Individual Park Items	Fitness Equipment	4	EA	Greenfields Outdoor Fitness	New	Elliptical, Three Person Static Combo, Recumbent Bike, Butterfly
	Benches	4	EA	Victory Stanley	New	Model C-138
	Bollards	4	EA		New	
	Trashcans	4	EA	Victory Stanley	New	Model FC-12, Black
	Paved Trails	1100	LF		New	

*Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations.
 ** Playground condition is based on visual inspection only and is not intended to be a CPSI level inspection
 ***GPS locations have been provided for all fixed park items, all moveable amenities are not included.

Neighborhood Park		Total Acreage				
Georgetown Park		2.4				
Type	Existing Amenities	Count	Units	Manufacturer	Condition**(*)	Notes
Shelters and Playgrounds	Playground	1	EA			Installed 2014;
	2-5	2	EA	Miracle (Hasley Recreation)	Good	Blue, Metallic, White
	5-12	1	EA	Miracle (Hasley Recreation)	Good	Blue, Metallic, White
	Swings	4	EA	Miracle (Hasley Recreation)	Good	Two tot swings, two regular swings
	Surfacing			EPDM	Good	
	Shade Structure	1	EA		Good	
	Shelter #1	1	EA		Good	Stone, Wood, Standing seam metal roof
	Trashcans	2	EA	Victor Stanley	Good	One trash, one recycle
	Benches	6	EA	Victor Stanley	Good	Backless model CM-158 benches
	Shelter #2	1	EA		Good	Stone, Wood, Standing seam metal roof
	Restroom #1	1	EA		Good	Stone, Wood, Standing seam metal roof
	Fountain	1	EA		Good	
	Restroom #2	1	EA		Good	Stone, Wood, Standing seam metal roof
	Fountain	1	EA		Good	
	Counts	Bocce Ball Court	2	EA		Good
Aquatics	Fountain	1	EA		N/A	Not in operation at time of visit
Individual Park Items	Fitness Equipment	2	EA	Greenfields	Good	Airwalker, Sit-up Bench
	Main Sign	3	EA		Good	Two stone signs, one Dunwoody P&R brand sign
	Benches	12	EA	Victor Stanley	Good	Four backless model CM-158 benches, eight model C-138 benches
	Bollards	9	EA		Good	
	Trashcans	9	EA	Victor Stanley	Good	Model FC-12, Black
	Bike Rack	2	EA		Good	
	Mutt Mitt Station	1	EA		Average	
	Paved Trails	1563	LF			

*Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations.
** Playground condition is based on visual inspection only and is not intended to be a CPSI level inspection
***GPS locations have been provided for all fixed park items, all moveable amenities are not included.

Neighborhood Park		Total Agerage				
Windwood Hollow Park		11.14				
Type	Existing Amenities	Count	Units	Manufacturer	Condition (**)	Notes
Shelters and Playgrounds	Playground	1	EA	Landscape Structures Inc		Installed 2014; plastic border
	2-5 Component Areas	1		Landscape Structures Inc	Good	Green, brown, lime
	5-12 Component Areas	1		Landscape Structures Inc	Good	Green, brown, lime
	Swings	5	EA	Landscape Structures Inc	Good	Two tot swings, two regular swings, one LSI Oodle Swing
	Other Equipment	1	EA	Landscape Structures Inc	Good	One track ride
	Surfacing			EPDM	Average	
	Benches	2		Landscape Structures Inc	Good	Benches are different model than park standard
	Shelter	1	EA		Average	Wood, Glulam, Shingle Roof
	Picnic Tables	8	EA	Wabash Valley	Average	Green and Black
	Trashcans	1	EA	Wabash Valley	Average	Black
Court Facilities	Tennis Court	2	EA			
	Fencing				Average	With windscreen
	Playing Surface				Average	
	Striping				Average	
	Benches	4	EA	Wabash Valley	Average	Green and Black
Individual Park Items	Fitness Equipment	4	EA	HealthBeat by Landscape Structures Inc	Good	Installed 2014
	Main Sign	1	EA		Good	
	Benches	3	EA	Wabash Valley	Average	Green and Black
	Water Fountains	1	EA		N/A	Fountain was winterized at time of visit; Green
	Trashcans	1	EA	Wabash Valley	Average	Black
	Unpaved Trails	1171	LF			

*Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations.
 ** Playground condition is based on visual inspection only and is not intended to be a CPSI level inspection
 ***GPS locations have been provided for all fixed park items, all moveable amenities are not included.

Pocket Park		Total Acentage				
Vernon Oaks Park		0.58				
Type	Existing Amenities	Count	Units	Manufacturer	Condition ^(**)	Notes
Individual Park Items	Main Sign	2	EA		Average	Durwoody Parks branded upright sign; old wooden sign
	Benches	2	EA		Average	Black; Metal
	Picnic Tables	1	EA		Poor	Wood
	Bridges (wooden)	1	EA		Poor	
	Unpaved Trails	614	LF			
^(*) Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations. ^(**) Playground condition is based on visual inspection only and is not intended to be a CPSI level inspection ^(***) GPS locations have been provided for all fixed park items, all moveable amenities are not included.						

Special-Use Park		Total Acentage				
Donaldson-Bannister Farm		3.11				
Type	Existing Amenities	Count	Units	Manufacturer	Condition ^(**)	Notes
Other Facilities	Misc. Structures	4	EA			Farm structures
Individual Items	Main Sign	1	EA			Durwoody Parks branded upright sign
^(*) Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations. ^(**) Playground condition is based on visual inspection only and is not intended to be a CPSI level inspection ^(***) GPS locations have been provided for all fixed park items, all moveable amenities are not included.						

Park Land		Total Acentage				
Perimeter Center Park		3				
Type	Existing Amenities	Count	Units	Manufacturer	Condition ^(**)	Notes
Individual Items	Main Sign	1	EA			Durwoody Parks branded upright sign
^(*) Condition: "Poor" being below expectations, "Average" indicating that the component can meet its intended function, and "Good" meaning that it exceeds expectations. ^(**) Playground condition is based on visual inspection only and is not intended to be a CPSI level inspection ^(***) GPS locations have been provided for all fixed park items, all moveable amenities are not included.						

THIS PAGE INTENTIONALLY LEFT BLANK